

Service Report

SV23029-2V



Customer:	ALUDEC S.A. Portugal	Date:	3-6.11.2025
Street:	Parque Emresarial de Lanhese, Lote B1	Technician:	M.Korzonkiewicz, M.Słowik
ZIP/City:	4925-412 Lanhese	Order No.(Customer):	0
Client:	Sérgio Santos	b+m No.:	SV23029-2V
System:	RVA 13446	Customer No.:	16336

Date				Work Time		Break	Drive	Work	km	Per Diem	Hotel Stay	Special Notes
	Day	Month	Year	from	to	Hrs.	Time	Time	Traveled			
Mo	3	11	25	7:00	16:00	0:00	9					
Tu	4	11	25	8:00	15:00	0:30		6.5				Work
We	5	11	25	8:00	14:00	0:30		5.5				Work
Th	6	11	25	7:00	18:00	0:00	11					
Fr						0:00						
Sa						0:00						
Su						0:00						
Total						1:00	20	12	0			

Fault/ Cause/ Measures:	Quote necessary?	Nein
--------------------------------	-------------------------	-------------

One of the flexible connections is slightly damaged (replacement required). the damage was covered with repair tape
 One of the temperature sensors have lower value than other (inspection or replacement required).
 The customer was left with two temperature sensors. One for storage, the other for replacement (the customer will do this themselves).

b+m surface systems GmbH
 Meiningen Weg 10
 36132 Eiterfeld
 phone: +49 (0) 66 72 - 92 92 - 100
 fax: +49 (0) 66 72 - 82 50
 e-mail: service@bm-systems.com
 web: www.bm-systems.com

Please confirm that you have received the report and that the listed services are correct

Nieprawidłowy podpis

X

Service Report EN
 Client (Customer)
 Podpisany przez: 977fab0f-a79b-48e1-9955-3552bc12ce95
 Sérgio Santos