


M= -38150
P= -162250

M= -38200
P= -162400

M= -38000
P= -162400



Pontos Notáveis		
Nº	M	P
1	-38081.967	-162331.150
2	-38081.974	-162331.400
3	-38074.092	-162330.967
4	-38074.027	-162331.969
5	-37924.305	-162331.802
6	-37924.195	-162332.768