

Job Report

SV23029-2RO



Customer:	ALUDEC S.A. Portugal	Date	11.12.2025
Street:	Parque Emresarial de Lanheses, Lote B1	Technician:	G. Szecowka
ZIP/City:	4925-412 Lanheses	Order No.(Customer):	23930
Client:	Sérgio Santos	b+m No.:	SV23029-2RO
System:	Paint Shop	Customer No:	16336

Date				Work Time			Drive Time	km Traveled	Per Diem	Hotel Stay	Special Notes
	Day	Month	Year	Part	Full	Over					
Mo	8	12	2025			x	0	0	x	x	
Tu	9	12	2025			x	0	0	x	x	
We	10	12	2025			x	0	0	x	x	
Th	11	12	2025	x			0	0	x	x	
Fr	12	12	2025				2,5	170	x		Air travel in total 10h
Sa											
Su	7	12	2025				2,5	170	x	x	Air travel in total 10h
Total								340			

Fault/ Cause/ Measures:	Quote necessary?	Nein
--------------------------------	-------------------------	-------------

Maintenance carried out according to checklists.

b+m surface systems GmbH
 Meininger Weg 10
 36132 Eiterfeld
 phone: +49 (0) 66 72 - 92 92 - 100
 fax: +49 (0) 66 72 - 82 50
 e-mail: service@bm-systems.com
 web: www.bm-systems.com

Please confirm that you have received the report and that the listed services are correct

X

Job Report EN
 Client (Customer)

Sérgio Santos